



January 18, 2018

To whom it may concern,

I am writing to you today to confirm garments made by, Delta Apparel Activewear **HAVE NOT** been produced with the Brominated Flame Retardants listed below:

No.	Name of Anatytes
1	Polybromobiphenyis (PBBs) Hexa BB
2	Tris(2,3-dibromopropyl) phosphate (TRIS)
3	Tris-(aziridiny)-phosphineoxide (Tris (1-aziridiny) phosphine oxide) or (TEPA)
4	Tetrabromodiphenyl ether (TetraBDE)
5	Pentabromodiphenyl ether(PentaBDE)
6	Hexabromodiphenyl ether (HexaBDE)
7	Heptabromodiphenyl ether (HeptaBDE)
8	Octabromodiphenyl ether(OctaBDE)
9	Decabromodiphenyl ether (DecaBDE)
10	Hexabromocyclododecane (HBCDD)
11	Tris(2-chloroethyl) phosphate (TCEP)
12	Tris(1,3-dichloro-2-propyl) phosphate (TDCPP) or (TDCP)

If you have any further question regarding these subject, please feel free to contact me at the following address:

Carlos Encalada  
VP.of Manufacture  
Delta Apparel  
2550 Premiere Pkwy, Suit 100  
Dulut,Georgia 30097  
011529818290262

Sincerely, Carlos Encalada 1/18/18